

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PED Dt. 23-01-1970)

1. Name of School : De Paul Public School, Thodupuzha
2. Name of the officer : Sudheesh P S (AE in charge)
3. Location : Thodupuzha, Idukki
4. Period for which the certificate is issued : 2026-'27
5. Type of building: 2 storeied building, RCC Roof, 57m x 8.40 m x 3.60m
6. Nature of defect if any : Nil
 - a) Foundation and basement :
 - b) Superstructure :
 - c) Doors and windows : Nil
 - d) Wood work wrought and put up :
 - e) Roof :
 - f) Flooring :
 - g) Miscellaneous (Crack if any) :
7. Any major defects noticed which will render the building unsafe in any manner: No major defects noticed
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting the classes: The structure is sound under normal weather conditions.

Note:

1. Instructions in item no. 9 in letter no. GEDN-MI/188 2025-G.EDN dtd 25 05 2026 should strictly be followed.

CERTIFICATE

Certified that the school was inspected by me on 17/09/2026 and found to be fit to conduct classes for the period 2026-'27 for the reason stated above.

Place: Thodupuzha

Date: 19/09/2026

(Seal)




Assistant Engineer

Thodupuzha Municipality

Assistant Engineer
Thodupuzha Municipality

3967 629-2026

24.06.2026

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD DL 23 - 01 - 1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

SHEMEENA MARACKAR.
[ASSISTANT ENGINEER]
DE PAUL PUBLIC SCHOOL
THODUPUZHA.

6 STORIED ROR BUILDING EXCLUDING
THIRD, FOURTH & TERRACE FLOOR.
BUILDING NOS: VII/438 & 508.
EXISTING BUILDING BASEMENT FLOOR.
- 29.97x6.66x3.10 M.
BASEMENT FLOOR II -
29.97x6.56x3.10 M.

5. Period for which the certificate is issued

24.06.2026 to
31.05.2027.

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

7. Any major defects noticed which will render the building unsafe in any manner

NIL

NIL

8. Whether maintenance works have been done properly

9. Whether the structure is sound or not for conducting classes

YES.

THE STRUCTURE IS SOUND UNDER
NORMAL WEATHER CONDITIONS.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Instructions in item no. 9 in letter no: GEON - M/188/2025 - G. EON
dt. 25.05.2026 should strictly be followed.
CERTIFICATE

certified that the school building was inspected by me on 24.06.2026 and

found to be fit / unfit to conduct classes, for the period 20.26-'27 for the reasons stated above.

Place: THODUPUZHA

Date: 24.06.2026



[Signature]
Assistant Engineer

Assistant Engineer
Thodupuzha Municipality